



6200 Northfront Rd.
Livermore, CA United States

Customer

Vehicle

2016 Toyota Camry Hybrid
VIN
4T1BD1FK4GU185874

Technician
2016

90,568 Mi In / 90,568 Mi
Out

Multi-Point Inspection

1. MPVI

✓ Pass: 42 ⚠ Caution: 2 ✗ Fail: 1 ⦿ Not Applicable: 3 ⓘ Refer Notes: 1

Tires

Tread Depth

Left Front	7 / 32"	✓	⚠	✗	⦿
Right Front	7 / 32"	✓	⚠	✗	⦿
Left Rear	7 / 32"	✓	⚠	✗	⦿
Right Rear	7 / 32"	✓	⚠	✗	⦿

Tire Pressure, Condition & Age

Left Front Tire Condition & Pressure	In: 35 psi	✓	⚠	✗	⦿
Right Front Tire Condition & Pressure	In: 35 psi	✓	⚠	✗	⦿
Left Rear Tire Condition & Pressure	In: 35 psi	✓	⚠	✗	⦿
Right Rear Tire Condition & Pressure	In: 35 psi	✓	⚠	✗	⦿
Reset Tire Pressure Monitor		✓	✗	⦿	
Wear Pattern/Damage		✓	✗	⦿	

Brakes

Brake System

Brake System (Including Lines, Hoses and Parking Brake)	✓	⚠	✗	⦿
---	---	---	---	---

Brake Pads

Left front	8 mm	✓	⚠	✗	⦿
Right front	8 mm	✓	⚠	✗	⦿
Left rear	7 mm	✓	⚠	✗	⦿
Right rear	7 mm	✓	⚠	✗	⦿
Inspect Rear Drum Brakes		✓	⚠	✗	⦿

Interior & Exterior

Check Damages

Floor mats	✓	⚠	✗	⦿
------------	---	---	---	---

Lights

Headlights/Turn Signals/High Beams/Fog Lights	✓	⚠	✗	⦿
Tail Lights/Turn Signals/Brake Lights/Reverse Lights	✓	⚠	✗	⦿
Exterior Lamps/Hazard Lights	✓	⚠	✗	⦿

Interior & Exterior

Wipers & Horn

Front Wipers	✓	⚠	✗	⦿
Rear Wiper	✓	⚠	✗	⦿
Horn	✓	⚠	✗	⦿

Under Hood

Fluid Levels

Engine Oil Level	✓	⚠	✗	⦿
Engine Cooling System	✓	⚠	✗	⦿
Power Steering Fluid	✓	⚠	✗	⦿
Brake Reservoir Fluid	✓	⚠	✗	⦿
Windshield Washer Fluid	✓	⚠	✗	⦿
Transmission Fluid	✓	⚠	✗	⦿
Drive axle	✓	⚠	✗	⦿
Transfer case	✓	⚠	✗	⦿

Filters & Cooling Systems

Cabin Air Filter	✓	⚠	✗	⦿
Engine Air Filter	✓	⚠	✗	⦿

Belts/Hoses/Spark Plugs

Belts: Engine, Accessory, Serpentine and/or V-drive	✓	⚠	✗	⦿
Cooling System Hoses	✓	⚠	✗	⦿
Heater/AC Hoses/Hydraulic Hoses and Connections	✓	⚠	✗	⦿

Battery

Battery Condition	✓ ⚠ ✖ ⦿
Battery voltage	12 Volts ✓ ⚠ ✖ ⦿

Under Vehicle

Steering/Suspension

Steering Components	✓	⚠	✗	⦿
Front Suspension Components	✓	⚠	✗	⦿



6200 Northfront Rd.
Livermore, CA United States

Customer

Vehicle

2016 Toyota Camry Hybrid
VIN
4T1BD1FK4GU185874

Technician
2016

Multi-Point Inspection

Under Vehicle

Steering/Suspension

Rear Suspension Components	☒ ☐ ☐ ☐
Exhaust System Components	☒ ☐ ☐ ☐

Transmission/Axle

CV Drive Axle Boots or Driveshafts & U-joints	☐ ☒ ☐ ☐
---	--

Check For Fluid Leaks

Engine Oil Leaks	☒ ☐ ☐ ☐
Cooling System Leaks	☒ ☐ ☐ ☐
Brake System Leaks	☒ ☐ ☐ ☐
Transmission System Leaks	☒ ☐ ☐ ☐
Steering System Leaks	☒ ☐ ☐ ☐

Inspection Notes

- ☒ CV Drive Axle Boots or Driveshafts & U-joints
INNER CV AXLE BOOT IS NOT LEAKING GREASE

Services

1.	MPVI	PERFORM CERTIFIED MULTI-POINT VEHICLE INSPECTION	Internal Pay	\$0.00
Current Estimate (incl. of Tax)				\$0.00
Recommendations Estimate				\$0.00
Current Estimate				\$0.00
Approved Total				\$0.00
Revised Estimate				\$0.00